## Mobile Crane Inspection Report



Job & Report Number	: J14542-SI01		Inspection Date:	17/10/2023		
Client / Equipment Holder: Agtrans Ltd.		Agtrans Ltd.		Contact Person:	Phill / CJ	
Address:		24 Fitzgerald Lane, Hawera		Contact Number:	0800 AGTRANS / 027 278 6770	
Туре:	Mobile	Crane		<b>Boom Configuration</b>	n: Hydraulic - teleboom	
Official Number:	68654			Rating Sheet:	Stored in cab	
Client ID:	LTM 1160-5.2			Capacity:	180T	
Manufacturer:	Liebherr			Hoist Rope Diamete	er: 21.0mmØ	
SWL Indicator Type:	e: Liebherr Liccon			Hooks SWL:	30.0T	
Vehicle Type: 2016 Liebherr LTM 1160-5.2			Registration:	NEN 953		

	GENERAL							
Number	Check	Assessment	Comments					
1	SWL & ID Cleary Visible	✓	Clear and well-marked. Satisfactory.					
2	Maintenance Records	✓	Maintained by Agtrans, crane in good condition.					
3	Rating Sheet (English, with Crane Number)	$\checkmark$	Liccon computer and hard copy in cab. Satisfactory.					
OPERATIONAL								
1	SLI Alarms (Visual, Audible, Cut-out)	$\checkmark$	Tested - Audible alarm and cut-out all operating. Satisfactory.					
2	Anti – Two Block, Main & Fly Jib	$\checkmark$	Tested main only rigged – Alarm and cut out. Satisfactory.					
3	Radius Indicator	$\checkmark$	Reading 24.2m at load test. Satisfactory.					
4	Boom Angle Indicator	$\checkmark$	Reading 35.1° at load testing. Overluffing alarm, cutout at 82.5°					
5	Load test (Load, Boom Length, Radius)	$\checkmark$	Tested using 3090T weight at 31.1m boom length Warning at 24.2m					
			and cut-out at 24.5m. As per tape and computer.					
6	Brake Test	✓	No creep noted during load testing. Satisfactory.					
CONDITION								
1	Cab (Controls, emergency Stop, Horn)	✓	Controls, E-stop and horn tested and in good working order.					
2	Outriggers	$\checkmark$	Good condition with no concerns noted. Well-marked for safety.					
3	Front Stabiliser Leg	N/A						
4	Wheels / Tyres / Tracks	$\checkmark$	10 x Tyres. No rips or tears noted. Good condition.					
5	Chassis & Super Structure	$\checkmark$	N rust or damage, in very good condition. Satisfactory.					
6	Hydraulic Rams & Hoses	С	Minor surface rust on main ram fitting, all others satisfactory.					
7	Slew Ring bearing & Bolts           ✓         Secure and in good operational condition. Satisfactory.		Secure and in good operational condition. Satisfactory.					
8			Well signed and in good condition and secure. Satisfactory.					
9	Brakes & Clutches (Wear Indicators)	$\checkmark$	No excessive wear noted. Satisfactory.					
10	Pawl Brake	✓ Activated at testing and in good working order. Satisfactory.						
11	Ropes (Terminations, Length) <ul> <li>Main rope rigged only and in good of the second second</li></ul>		Main rope rigged only and in good condition. 21mm Ø.					
12	Sheaves ✓ Satisfactory condition.		Satisfactory condition.					
13	King Post & Luffing Gear	✓	Clean and tidy condition with no concerns noted. Satisfactory.					
14	Boom / Jib (Wear Pads & Extension Ropes)	$\checkmark$	5 x Ext. Visually in good condition.					
15	Fly Jib & Attachments	C	Stored in yard at time of inspection. Not seen.					
16	Hooks & Blocks	✓	30T Bull horn Hook – Y-160, actual =160mm both sides.					
17	Other	С	Wind gusts at 17m/S at time of inspection – Wind speed alarm					
			working.					
LEGEND								
✓ Acceptable C Comment								
× No	× Not Acceptable NA Not Applicable							



This item has been inspected in accordance with the relevant codes & standards and is being recommended for certification.

## Expiry Date: 29/11/2024

Equipment Inspector: Alan Winch		Reviewed By: Peter George
Alan Winch – Authorised Signatory	FOCREDITED	R.A.

## Mobile Crane Inspection Report



Cra	SENTINEL INSPECTION SERVICES LTD.						
Client:	Agtrans Ltd.	Job Number:	J14542-SI01				
Controller:	Phill/CJ	Date of Inspection:	17/10/2023				
Controller's	24 Fitzgerald Lane, Hawera	Official Number:	68654				
Address:	dress: Taranaki		180.0 Ton (Max)				
Equipment ID:	LTM 1160-5.2	Manufacturer:	Liebherr - 2016				
Equipment Desc: Mobile Crane – Reg: NEN 953		Crane Type:	Mobile				
Purpose:	Purpose: Customer lifting requirements						
Location:	ocation: New Zealand Wide		29/11/2024				
This equipment was found to be in a satisfactory and safe condition at the time of inspection and will remain safe for the period of the certificate if operated and maintained properly.							
Equipment Inspector:       A.Winch       Authorised Signatory:       A.Winch							
Sentinel Inspection Services Ltd. is an IANZ Accredited Inspection Body         All enquires phone (06) 281 1302         www.sentinelltd.co.nz							