

Truck Mounted Crane Inspection Report

(Knuckle Boom & Straight Boom)



Job & Report Number:	J5723-SI01	Inspection Date:	05/02/2019
Client / Equipment Holder:	Agtrans Ltd	Contact Person:	Phill / CJ
Address:	24 Fitzgerald Lane, Hawera.	Contact Number:	0800 AGTRANS / 027 278 6770
Type:	Truck Mounted Crane	Boom Configuration:	Knuckle Boom
Official Number:	SIS128035	Rating Sheet:	Posted on crane
Client ID:	DFF 731	Capacity:	As per rating chart (max 5850kg).
Manufacturer:	Palfinger PK 17.001SLD	Hoist Rope Diameter:	n/a
SWL Indicator Type:	Alarms & Cut-outs	Hooks SWL:	8.0 ton
Vehicle Type:	2006 Mercedes Benz	Registration:	DFF 731

GENERAL

Number	Check	Assessment	Comments
1	ID Number Visible	✓	Clearly marked.
2	Maintenance Records	✓	In order.
3	Load Radius Rating Chart (English)	✓	Posted near crane control. In good order.
4	LT 400 (Only on First Inspection)	n/a	

OPERATIONAL

1	Overload Protection System	✓	Audio and visual alarms & cut-outs. In good working order.
2	Anti – Two Block (recommended)	n/a	
3	Load Holding Valves (if required)	✓	
4	Load Test	✓	Function tested satisfactorily.
5	Stability Check (if required)	✓	No concern noted.
6	Sag Rate	✓	
7	Stabiliser Check valves (if required)	✓	Rear mounted. Satisfactory.
8	Hoist Winch	n/a	
9	Hydraulics	✓	In good order.
10	Controls	✓	Local & remote controls, in good order. Emergency stops, in good order.
11	Extensions (visible locks, position indicator)	✓	4 x hydraulic extensions. In good order.

CONDITION

1	Crane Mounting (base stops, spacers)	✓	In good order.
2	Crane Base (bolting, pins, bushes, locks)	✓	In order.
3	Extension Beam(s) & Jacks	✓	All satisfactory order.
4	Extensions (wear pads, locks)	✓	In good order.
5	Slew Bearing / Slew bearing / Bolts	✓	No anomalies noted.
6	Crane Body (bolting, pins, bushes, locks)	✓	In order.
7	Inner Boom (pins, bushes, locks)	✓	In order.
8	Outer Boom (pins, bushes, locks)	✓	In order.
9	Extending Booms (wear pads)	✓	Satisfactory.
10	Hooks & Hook attachments	✓	8.0 ton SWL hook, satisfactory.
11	Ropes (terminations, length)	n/a	
12	Sheaves	n/a	
13	Hydraulic Tank & Hoses	✓	All, in good order.
14	Other	C	Crane year, 2017. Serial no. 100407564.

LEGEND

✓	Acceptable	C	Comment
✗	Not Acceptable	NA	Not Applicable

Additional Comments / Photos:



This item has been inspected in accordance with the relevant codes & standards and ~~not being~~ / is being recommended for certification.

Expiry Date: 04/02/2020

Equipment Inspector:	Reviewed By:
B.Mohan – IANZ Signatory 	

Truck Mounted Crane Inspection Report

(Knuckle Boom & Straight Boom)



Truck Crane Certificate of Inspection



Client: Agtrans Limited. Address: 24 Fitzgerald Lane, Hawera. Controller: Phill / CJ Client ID: DFF 731 Location: New Zealand Wide. Type / Description: Truck Mounted Crane Vehicle Type / Reg: 2006 Mercedes Benz/DFF 731 Year / Serial no: 2017 / 100407564.	Job Number: J5723-SI01 Date Inspected: 04/02/2019 Official Number: SIS128035 Capacity: As per chart (max 5850kg). Hoist Rope Diameter: n/a Hook SWL: 8.0 tonnes Manufacturer: Palfinger PK 17.001SLD Date of Expiry: 04/02/2020
<i>This equipment was found to be in a satisfactory and safe condition at the time of inspection and will remain safe for the period of the certificate if operated and maintained properly.</i>	
Equipment Inspector: B.Mohan – IANZ Signatory.	