

Proof test type:

KEY: $1 = Safe \ 2 = Action \ next \ inspection \ 3 = Repair \ 4 = Renewal \ Required \ x = N/A$

OBSERVATIONS & DEFECTS

New 3-axle crane with max capacity 50t at 3.0m. Boom length 8.1m to 36m in 5 sections plus fly 7.5m + needle 5.5m Seen with no rooster fitted so only one winch operational. A new rooster is to come but some 6 weeks away. Counterweight 6.5t

Hook: 3 sheave ramshorn, max SWL 40t M3, 919785508E, 22.0178.05, Wt 280kg, YY = 140, \oplus 15mm.

Tested with 7.5t counterweight, showing 8.3t on screen

90% reached at 11.2m on screen, confirmed by tape

100% reached at 12m on screen, confirmed by tape

110% reached at 12.7m on screen, confirmed by tape

125% reached at 13.4m on screen, confirmed by tape

Emergency stops in cab and at rear of car body proved satisfactory.

Cab extension proved satisfactory.

TEST EOUIPMENT

ID No. 7.5t

Type Counterweight

Calibration details Manufacturer

71	0			
	SIGNATORY:	BM George	Issue date: 14/06/23	
	D1 0 D '11' 0 C		·	

Plant & Building Safety Ltd is an I.A.N.Z. accredited Inspection Body

This report may only be reproduced in full. Standard terms and conditions apply, and may be viewed at www.pbsl.co.nz This report is issued exclusively to the Owner and must not be used for other purposes without our permission

PO Box 19-789 C	hristchurch N	LDING SAFETY LTD tchurch NZ www.pbsl.co.nz FICATE OF INSPECTION Certificate No. G 21400						
Owner / Controller	Agtrans							
UNIQUE NO. OF ITEM: PBSL G21400 : 043 991								
Description/Purpose	Maker	Location	SWL	. (t)				
LTC 1050-3.1	Liebherr	Nationwide	Refer to Ma	ker's sheets				
This item has been inspected in accordance with the HSE (PECPR) Regulations 1999, and was found to be safe at the time of inspection. Subject to proper operation and maintenance, this equipment may remain in use for the period of this certificate. THIS CERTIFICATE EXPIRES ON: 14/06/24								
Refer to separate report for Surveyor's recommendations								
ignatory: BM George Inspector: BM George Issue date: 14/06/23 Plant & Building Safety Ltd is an I.A.N.Z. accredited Inspection Body This certificate may only be reproduced in full Standard terms and conditions apply, and may be viewed at www.pbsl.co.nz								