## Mobile Crane Inspection Report



Job & Report Number:		J20785-SI03	Inspection Date:	10/04/2025
Job & Report Number:		120785-3103	inspection bate.	10/04/2023
Client / Equipment Holder:		Agtrans Ltd	Contact Person:	Phill/CJ
Address:		24 Fitzgerald Lane, Hawera	Contact Number:	0800AGTRANS/ 0272786770
Туре:	Magni	- Telescopic Handler / Crane Attachment	Boom Configuration:	Teleboom with fixed hook attachment.
Serial Number:	Mobile Unit: 00006186– Hook : AC018662		Rating Sheet:	On tag 6000kg / Computer
Client ID:	RTH 6.25-D/A Telehandler with H61 Attachment		Capacity:	6000kg (Max)
Manufacturer:	lanufacturer: Magni- 2022		Hook attachment:	H61- No: L52487 - S/N: AC017582 - SWL 6000kg
SWL Indicator Type: Alarm, Cut out		Cut out	Hooks SWL:	Attacmnet H61: 6000kg / Hook SWL 8.0t
Vehicle Type: Mobile Crane / Telehandler		Registration:	PPH572	

		GE	NERAL			
Number	Number Check		Comments			
1	SWL & ID Cleary Visible	<b>✓</b>	Crane	Crane - ID plate in cab / Winch – ID plate on side of attachment.		
2	2 Maintenance Records		Maintained inhouse by Agtrans own team			
3	3 Rating Sheet (English, with Crane Number)		Magni	Magni load computer and chart. Satisfactory		
		OPER	RATIONA			
4	4 SLI Alarms (Visual, Audible, Cut-out)		Tested audio, visual and Cut-Out. Incl reverse alarm. Satisfactory.			
5	Anti – Two Block, Main & Fly Jib	С	Fixed hook unit – H61 used for testing.			
6	Boom Angle Indicator	✓	Satisfa	Satisfactory operating, luffing limiter set to 78.1°		
7	7 Load test – Legs down		Using	Using 840kg, alarm at 16.9m, cut-out at 17.4m Comp reading 17.34		
	(Load, Boom Length, Radius)		with b	vith boom length 19.64m, 7.5° Boom angle		
8	Interlock – Legs down under load		Under	Under load legs would not fold away and locked out. Satisfactory.		
9	Load test- Legs up (On Rubber)	✓	Using	840kg, alarm at 11m, cut-out at 11.3m comp reading 11.35		
	(Pick and carry mode)		Boom	length 13.6m, 10.8° Boom angle.		
10	Interlock – Slew Limiter on rubber		Under	load slew limiter cut out at 2° during testing. Satisfactory.		
	Interlock – Bonnett up vehicle locks out		Tested	l and working satisfactory.		
11	Brake Test	✓	Holdin	g satisfactory during load testing.		
			NOITION			
12	Cab (Controls, emergency Stop, Horn)	✓	ESD ar	nd horn working with well labelled controls. Satisfactory.		
13	Outriggers	✓	4 x ou	triggers in good condition and operating satisfactory.		
15	Wheels / Tyres / <del>Tracks</del>	✓	4 x tyr	4 x tyres in good serviceable condition.		
16	Chassis & Super Structure	С	Startir	Starting to rust in places – Recommend paint maintenance.		
17	Hydraulic Rams & Hoses	✓	Satisfa	Satisfactory condition with no concerns noted.		
18	Slew Ring bearing & Bolts	✓	Secure and in good operating condition. Satisfactory.			
19	Counterweight & Signage	✓	Built in	Built into chassis and in satisfactory condition.		
20	Brakes & Clutches (Wear Indicators)	✓	Satisfactory.			
21	Pawl Brake	✓	Fully tested and operating satisfactory.			
22	Ropes (Terminations, Length)	С	Fixed hook unit used for testing.			
24 King Post & Luffing Gear		✓	Satisfactory condition.			
25	Boom / Jib (Wear Pads & Extension Ropes) ✓ S		Secure and no uneven or excessive wear noted. Satisfactory			
26			H61 C	H61 Crane attachment. Satisfactory condition.		
27			8.0t S\	8.0t SWL Hook and clasp in satisfactory condition.		
28	Other	✓	Unit H	Unit H61 attachment designates unit as a Tele boom fixed hook.		
		LE	GEND			
	cceptable		С	Comment		
× No	ot Acceptable		NA	Not Applicable		















 $This item \ has been \ in spected \ in \ accordance \ with \ the \ relevant \ codes \ \& \ standards \ and \ \emph{is being} \ recommended \ for \ certification.$ 

Expiry Date: 30/04/2026

Equipment Inspector: A.Winch		Reviewed By: Mark Bright	
Alan Winch – Authorised Signatory	RESPECTION SO	M.Bright	

## Mobile Crane Inspection Report



	Actions	
Action		Priorit
Item 16: Chassis and superstructure becoming rusty – recommen	d maintenance	R
Priority: M Mandatory by certificate expiry	R	Recommendation

