

Mobile Crane Inspection Report



| | | | |
|---------------------------------|-------------|-------------------------|------------|
| Job & Report Number: | J23749-SI02 | Inspection Date: | 04/05/2026 |
|---------------------------------|-------------|-------------------------|------------|

| | | | |
|-----------------------------------|-----------------------------|------------------------|-----------------------------|
| Client / Equipment Holder: | Agtrans Limited | Contact Person: | Logan Willeman |
| Address: | 24 Fitzgerald Lane, Hawera, | Contact Number: | 0800 AGTRANS / 027 588 9010 |

| | | | |
|----------------------------|------------------------------------|-----------------------------|-------------------------------------|
| Type: | Mobile Crane | Boom Configuration: | 5 x Hydraulic Tele-boom |
| Official Number: | PBSLG21508: 086318 | Rating Sheet: | Incorporated in Liebherr Loadmaster |
| Client ID: | Reg: QNQ538 - Liebherr LTM1070-4.2 | Capacity: | 70 tonnes |
| Manufacturer: | Liebherr 01/2024 | Hoist Rope Diameter: | Main and Auxiliary - 17mm Ø |
| SWL Indicator Type: | Liebherr Loadmaster computer | Hooks SWL: | 40 ton |
| Vehicle Type: | Liebherr 1/2024 | Registration: | QNQ538 |

GENERAL

| Number | Check | Assessment | Comments |
|--------|---|------------|--|
| 1 | SWL & ID Clearly Visible | ✓ | Company logo and ID plate on cab. Satisfactory |
| 2 | Maintenance Records | ✓ | Maintenance performed by Agtrans technicians. Satisfactory. |
| 3 | Rating Sheet (English, with Crane Number) | ✓ | Liebherr loadmaster computer and hard copy in cab. Satisfactory. |

OPERATIONAL

| | | | |
|---|---------------------------------------|---|--|
| 1 | SLI Alarms (Visual, Audible, Cut-out) | ✓ | Audible, visual alarms and cut-out tested. Satisfactory. |
| 2 | Anti – Two Block, Main & Fly Jib | ✓ | Main and Auxiliary alarm and cut-out. Satisfactory. |
| 3 | Radius Indicator | ✓ | Reading 19.8m at load test. Accurate according to tape. |
| 4 | Boom Angle Indicator | ✓ | Reading 61° at load test. Satisfactory. |
| 5 | Load test (Load, Boom Length, Radius) | ✓ | Using 4t, Warning at 19.5m and cut-out at 20.6m. Boom length 39.7m |
| 6 | Brake Test | ✓ | No creep noted during all testing. Satisfactory. |

CONDITION

| | | | |
|----|--|-----|--|
| 1 | Cab (Controls, emergency Stop, Horn) | ✓ | Remote, horn tested. E stop tested and reset. Satisfactory. |
| 2 | Outriggers | ✓ | 4 x outriggers in good tidy condition. Satisfactory. |
| 3 | Front Stabiliser Leg | N/A | |
| 4 | Wheels / Tyres / Tracks | ✓ | 8x wheels in satisfactory condition. |
| 5 | Chassis & Super Structure | ✓ | Good tidy condition. Satisfactory. |
| 6 | Hydraulic Rams & Hoses | ✓ | Satisfactory condition. |
| 7 | Slew Ring bearing & Bolts | ✓ | Bolting secure and bearing in good condition. |
| 8 | Counterweight & Signage | ✓ | 9.3t fitted for inspection. Satisfactory warning signs. |
| 9 | Brakes & Clutches (Wear Indicators) | ✓ | Satisfactory condition. |
| 10 | Pawl Brake | ✓ | Tested in all positions and in good operating condition. Satisfactory. |
| 11 | Ropes (Terminations, Length) | ✓ | Both 17mmØ ropes inspected. Good dead ends. Satisfactory. |
| 12 | Sheaves | ✓ | Satisfactory condition. |
| 13 | King Post & Luffing Gear | ✓ | Over luff cut out at 83.2°. Tidy condition. Satisfactory. |
| 14 | Boom / Jib (Wear Pads & Extension Ropes) | ✓ | 5 x extension, Wear pads and extensions in good condition |
| 15 | Fly Jib & Attachments | ✓ | Fly and jib in good condition with all pins and retainers. |
| 16 | Hooks & Blocks | ✓ | 40.0ton SWL. Y-180 in good condition. 6t SWL aux. y-axis-120 |
| 17 | Other | ✓ | Crane is generally in good condition |

LEGEND

| | | | |
|---|----------------|----|----------------|
| ✓ | Acceptable | C | Comment |
| ✗ | Not Acceptable | NA | Not Applicable |

- Crane Commissioned by "Plant and Building" - 17/04/2024

Additional Comments / Photos: Crane year mfg. 2024. S/N: 086 318



This item has been inspected in accordance with the relevant codes & standards and is being / ~~not being~~ recommended for certification.

Expiry Date: 31/05/2027

| | |
|----------------------------------|---------------------------|
| Equipment Inspector: Mark Bright | Reviewed By: Alan Winch |
| A.Winch – Authorised Signatory | Alan Winch |
| | Date of Issue: 05/05/2026 |

Mobile Crane Inspection Report



| Actions | | Priority |
|-----------|-----------------------------------|------------------|
| Action | | |
| Nil. | | |
| Priority: | M Mandatory by certificate expiry | R Recommendation |

Crane Certificate of Inspection

| | |
|--|---|
| <p>Client: Agtrans Limited</p> <p>Controller: CJ</p> <p>Controller's Address: 24 Fitzgerald Lane, Hawera Taranaki</p> <p>Equipment ID: Reg: QNQ538</p> <p>Equipment Desc: Liebherr LTM1070-4.2</p> <p>Purpose: Customer Lifting Requirements</p> <p>Location: New Zealand Wide</p> | <p>Job Number: J23749-SI02</p> <p>Date of Inspection: 04/05/2026</p> <p>Official Number: PBSLG21508: 086 318</p> <p>Safe Working Load: 70.0t at 2.5m (Max)</p> <p>Manufacturer: Liebherr – 01/2024</p> <p>Crane Type: Mobile</p> <p>Serial Number: 086318</p> |
| <p>Date of Expiry: 31/05/2026</p> | |
| <p><i>This equipment was found to be in a satisfactory and safe condition at the time of inspection and will remain safe for the period of the certificate if operated and maintained properly.</i></p> | |
| <p>Equipment Inspector: Mark Bright Authorised Signatory: A.Winch</p> | |
| <p>Sentinel Inspection Services Ltd. is an IANZ Accredited Inspection Body All enquires phone (06) 281 1302</p> | |
| <p>www.sentineltd.co.nz</p> | |
| | |
| <p>No. 128</p> | |